




Dim	Min
P1	5.72
P2	4.00
Q1	1.00
Q2	0.90




Dim	Min
P1	6.00
P2	2.40
Q1	1.84
Q2	1.20




Dim	Min
P1	6.00
P2	2.40
Q1	1.84
Q2	1.20




Dim	Min
P1	8.73
P2	5.12
Q1	2.22
Q2	1.2




Dim	Min
P1	8.73
P2	5.12
Q1	2.22
Q2	1.2



Dim	Min
P1	9.15
P2	7.10
Q1	1.80
Q2	2.00




Dim	Min
P1	5.58
P2	1.66
Q1	1.96
Q2	2.04




Dim	Min
P1	3.90
P2	2.70
Q1	1.10
Q2	0.78







Dim	Min
P1	5.90
P2	2.70
Q1	1.60
Q2	1.90



Dim	Min
P1	5.80
P2	1.76
Q1	2.07
Q2	2.72



Dim	Min
P1	9.9
P2	3.84
Q1	3.03
Q2	3.82



Dim	Min(mm)
A	3.36
B	4.86
C	0.85
P	1.84
Q1	1.4
Q2	1.4